Pantheon Saloon/Red Front Roofs – **Existing Conditions**

KLGO 331433A
April, 20

Exhibit B

Scupper located in bottom right of photo where repairs were made in 2023. Black “Henry’s Roof Patching” compound applied to attempt to seal suspected areas of water infiltration.

Pantheon Saloon/Red Front Roofs – **Existing Conditions**

Chimney East View

Chimney South View

Pantheon Saloon/Red Front Roofs – **Existing Conditions**

Chimney West View

Chimney North View