Initial Annual Fire & Smoke Door Inspection

Faletti Construction LLC
Manchester Va
718 Smyth Road
Manchester, NH 03104

Inspection No.:	SLS484561
Code Edition:	NFPA 80 - 2010 for Healthcare
Inspection Initiated:	August 26 2024

If the report indicates that deficiencies were found (and were not repaired on-site), please refer to corresponding proposal.
This comprehensive FireCheck® inspection report is based on NFPA 80 (fire) and NFPA 105 (smoke) requirements. This report applies only to door list provided by the Customer.

Code Interpretation Disclaimer: All information provided by DH Pace Inc. represents our interpretation regarding the intent of the standard(s) and/or code(s) applicable to the issue being addressed. By law, the Authority Having Jurisdiction (AHJ) is the only entity with the legal standing and discretionary authority to make a definitive ruling on these matters. As such, DH Pace disclaims any consequential damages that may arise from the use of the information provided, recommendation made, or opinions expressed on this matter.

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Summary

Name	Manchester Va	**Contact**	Faletti, Alex
Address	718 Smyth Road	**Contact #**	(801) 201-8438
City, State Zip	Manchester, NH 03104	**Inspection Dates**	8/26/2024 To 9/18/2024

P/F	Initial	Repaired	Post Repair
Pass	55	32	87
Fail	52	5	20
Total	107	37	



Priority of Failed Openings	Opening #
Critical	6
Immediate	12
Essential	1
Total Failed	**20**

Priority Definitions

Critical - Deficiency requires urgent corrective action without delay
Immediate - Deficiency requires corrective action without delay
Essential - Deficiency requires corrective action, safety concern



Owner to remove excess signage.
Owner to verify rating of protection plates, electric strikes, power transfer cords, presence sensors, door position/alarm sensors, steel pick guards, door/frame guards, gasketing/perimeter seal, door viewers, and auto door bottoms/sweeps.

DHI IVAN ALBERT, CFDAI No. 147141 VALID THROUGH OCT. 2025 CERTIFIED CONSULTANT

Name: Ivan Albert - CFDAI Signature: Date: **9/18/2024**

Ivan Albert
Main: (516) 317-9495
Email: Ivan.Albert@dhpace.com

DH Pace Compliance Services
3035 Horseshoe Lane, Suite R
Charlotte, NC 28208
(704) 527-5379

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Criteria

Name	Manchester Va	**Code Edition:**	
Address	718 Smyth Road Manchester, NH 03104	NFPA 80 - 2010 for Healthcare	
Inspection Dates	8/26/2024 To 9/18/2024	**Inspection No.**	SLS484561

Criteria	Components	Description	# Failed Openings
FC1	Frame, Door	No open holes or breaks exist in surfaces of either the door or frame.	**3**
FC2	Frame, Door	Glazing, vision light frames, and glazing beads are intact and securely fastened in place, if so equipped. Safety glass is the correct size and type.	**0**
FC3	Frame, Door, Hardware	The door, frame, hinges, hardware and non-combustible threshold are secured, aligned, and in working order with no signs of visible damage.	**0**
FC4	Frame, Door, Hardware	No parts are missing or broken.	**4**
FC5	Top, Bottom, Hinge Edge, Strike Edge	Door clearances do not exceed clearances listed in 4.8.4 and 6.3.1.7. WOOD/PLAM EDGES/TOP not > 1/8", WOOD/PLAM BOTTOM not > 3/4", HM-STEEL EDGES/TOP 1/8" + or - 1/16", HM-STEEL BOTTOM not > 3/4"	**4**
FC6	Hardware	The self-closing device is operational, that is, the active door completely closes when operated from the full open position.	**2**
FC7	Hardware	If a coordinator is installed, the inactive leaf closes before the active leaf.	**0**
FC8	Hardware	Where latching hardware is required, it operates and secures the door when it is in the closed position (not required for cross-corridor doors 1-hr Smoke Barriers in Healthcare deemed "Substantial Doors" and not 20-min rated/labeled)	**4**
FC9	Hardware	Auxiliary items that interfere or prohibit operation are not installed on the door or frame.	**0**
FC10	Frame, Door, Hardware	No field modifications to the door assembly have been performed to void the label.	**6**
FC11	Frame, Door	Gasketing and edge seals, where required, are inspected to verify their presence and integrity.	**0**
FC12	Size, Mounting	Signage is the correct size and mounted properly.	**1**
FC13.D	Door	Labels are present and readily visible on the opening door.	**2**
FC13.F	Frame	Labels are present and readily visible on the opening frame.	**2**
FC13.G	Glass	Labels are present and readily visible on the opening glass.	**0**
FC13.H	Hardware	Labels are present and readily visible on the opening hardware.	**0**
FC13.P	Protection Plate	Labels are present and readily visible on the protection plate (when plate is mounted above 16" from bottom of door)	**0**
FC14	Hardware	Doors installed in pressurized applications have gasketing and a bottom seal (note deficient gasketing on FC11)	**0**
FC15	Hardware	No louvers or transfer grills in door (when door is in combo fire and smoke barrier or just smoke barrier)	**1**

Door Type

S - Single | UP - Unequal Pair | P - Pair | DE - Double Egress | B - Bank | D - Dutch

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1
Floor: 1

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0072	265-410299-001-0072	Passed	STAIR E 137	Ivan Albert	9/06/2024
Single	Hollow Metal	46" (3'10") x 84"	Hollow Metal Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0073	265-410299-001-0073	Passed	WAITING RM E129	Ivan Albert	9/06/2024
Pair	Wood	44" (3'8") x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

0074	265-410299-001-0074	Passed	STAIR #1 E111	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0075	265-410299-001-0075	Passed	ELECTRICAL CL E110	Ivan Albert	8/27/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0077	265-410299-001-0077	Passed	ELECTRICAL CL N145	Kevin Sheehan	9/18/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

0077	265-410299-001-0077	Passed	ELECTRICAL CL N145	Ivan Albert	8/27/2024
Single	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0078	265-410299-001-0078	Passed	CORRIDOR N147A	Ivan Albert	8/27/2024
Double Egress	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

0079	265-410299-001-0079	Passed	STAIR #4 N126	Kevin Sheehan	9/16/2024
Single	Hollow Metal	32" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0080	265-410299-001-0080	Passed	STAIR #3 W145	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1
Floor: 1

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0081	265-410299-001-0081	Passed	SPRINKLER CONTROL	Ivan Albert	8/27/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0082	265-410299-001-0082	Passed	ELECTRICAL CL W146	Ivan Albert	8/27/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0083	265-410299-001-0083	Failed	VESTIBULE NW141	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Critical

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC6

0084	265-410299-001-0084	Passed	VESTIBULE NW141	Kevin Sheehan	9/16/2024
Pair	Wood	46" (3'10") x 90"	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

0085	265-410299-001-0085	Passed	EMER ELECTR SW103	Ivan Albert	8/27/2024
Single	Wood	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0086	265-410299-001-0086	Passed	ELECTRICAL CL SW102	Ivan Albert	8/27/2024
Single	Wood	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0087	265-410299-001-0087	Failed	OFFICE NW101	Ivan Albert	9/06/2024
Single	Wood	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC4

Floor: 2

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0063	265-410299-001-0063	Passed	STAIR #1 E209	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1
Floor: 2

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0064	265-410299-001-0064	Passed	ELECTIRCAL CL E210	Kevin Sheehan	9/16/2024
Single	Hollow Metal	30 x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0065	265-410299-001-0065	Passed	STAIR #2 N286	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0066	265-410299-001-0066	Passed	ELECTRICAL CL N285	Kevin Sheehan	9/18/2024
Single	Hollow Metal	30 x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0067	265-410299-001-0067	Passed	STAIR #4 N273	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0068	265-410299-001-0068	Passed	ELECTRICAL CL N 272	Kevin Sheehan	9/16/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0069	265-410299-001-0069	Passed	ELECTRICAL CL W255	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

0070	265-410299-001-0070	Passed	STAIR #3 W246	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0071	265-410299-001-0071	Passed	ELECTRICAL CL W247	Kevin Sheehan	9/16/2024
Single	Hollow Metal	30" x 80"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0148	265-410299-001-0148	Passed	ELECTRICAL W154A	Ivan Albert	8/27/2024
Pair	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1
Floor: 2

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0149	265-410299-001-0149	Passed	CHAPEL N267	Ivan Albert	9/06/2024
Single	Wood	42" (3'6") x 84"	Hollow Metal Not Filled	1-Hour Smoke Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	20 mins	N/A	N/A

Floor: 3

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0053	265-410299-001-0053	Passed	STAIR #1 E316	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0054	265-410299-001-0054	Passed	ELECTRICAL CL E315	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0055	265-410299-001-0055	Passed	ELECTRICAL CL N389	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0056	265-410299-001-0056	Passed	STAIR - N390	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0057	265-410299-001-0057	Passed	STAIR #4 N375	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0058	265-410299-001-0058	Passed	ELECTRICAL CL N376	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0059	265-410299-001-0059	Passed	ELECTRICAL C W357A	Ivan Albert	8/26/2024
Pair	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1
Floor: 3

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0061	265-410299-001-0061	Passed	STAIR #3 W349	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0062	265-410299-001-0062	Passed	ELECTRICAL CL W350	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

Floor: 4

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0044	265-410299-001-0044	Passed	STAIR #1 E415	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0045	265-410299-001-0045	Passed	ELECTRICAL CL E414	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0046	265-410299-001-0046	Passed	STAIR #2 N498	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0047	265-410299-001-0047	Passed	ELECTRICAL CL N497	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0048	265-410299-001-0048	Passed	STAIR #4 N481	Ivan Albert	9/06/2024
Single	Hollow Metal	44" (3'8") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0049	265-410299-001-0049	Passed	ELECTRICAL CL N480A	Ivan Albert	9/06/2024
Single	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1
Floor: 4

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0050	265-410299-001-0050	Passed	ELECTRICAL CL W453	Ivan Albert	8/26/2024
Pair	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

0051	265-410299-001-0051	Passed	STAIR #3 W446	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0052	265-410299-001-0052	Passed	ELECTRICAL CL W447	Kevin Sheehan	9/16/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

Floor: 5

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0033	265-410299-001-0033	Passed	STAIR #1 E515	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0034	265-410299-001-0034	Passed	ELECTRICAL CL E514	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0035	265-410299-001-0035	Passed	STAIR #2 N578	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0036	265-410299-001-0036	Passed	ELECTRICAL CL N577	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0037	265-410299-001-0037	Passed	STAIR N565	Kevin Sheehan	9/18/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1
Floor: 5

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0038	265-410299-001-0038	Passed	CORRIDOR N569A	Ivan Albert	9/06/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0039	265-410299-001-0039	Failed	MECHANICAL N566	Kevin Sheehan	9/16/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC13.F

0040	265-410299-001-0040	Passed	MECHANICAL N567	Ivan Albert	8/26/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0041	265-410299-001-0041	Passed	ELECTRICAL CL W566	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

0042	265-410299-001-0042	Passed	ELECTRICAL CL W549	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0043	265-410299-001-0043	Passed	STAIR #3 W548	Ivan Albert	9/06/2024
Single	Hollow Metal	44" (3'8") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

Floor: 6

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0025	265-410299-001-0025	Passed	STAIR #1 E614	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0026	265-410299-001-0026	Passed	ELECTRICAL CL E613	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1

Floor: 6

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0027	265-410299-001-0027	Passed	ELECTRICAL CL N661	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0028	265-410299-001-0028	Passed	STAIR #2 N662	Kevin Sheehan	9/16/2024
Single	Hollow Metal	44" (3'8") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0029	265-410299-001-0029	Passed	STAIR N653	Ivan Albert	8/26/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0030	265-410299-001-0030	Passed	ELECTRICAL CL W645	Ivan Albert	9/06/2024
Pair	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

0031	265-410299-001-0031	Failed	STAIR #3 W638	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Essential

0031	265-410299-001-0031	Passed	STAIR #3 W638	Ivan Albert	9/06/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

Floor: 7

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0024	265-410299-001-0024	Passed	STAIR #2 E703	Ivan Albert	8/26/2024
Single	Hollow Metal	44" (3'8") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

Floor: B

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0091	265-410299-001-0091	Passed	STAIR #1 E07	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1
Floor: B

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0092	265-410299-001-0092	Passed	ELECTRICAL CL E06	Ivan Albert	9/06/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0094	265-410299-001-0094	Failed	STAIR #2 N100	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC1, FC4, FC5

0095	265-410299-001-0095	Passed	ELECTRICAL CL N99	Ivan Albert	8/27/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0096	265-410299-001-0096	Failed	STAIR #2 N100	Ivan Albert	9/06/2024
Single	Hollow Metal	48" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Critical

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC1, FC8

0097	265-410299-001-0097	Passed	ROOM NE103	Ivan Albert	8/27/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0098	265-410299-001-0098	Passed	CORRIDOR N89	Kevin Sheehan	9/18/2024
Double Egress	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

0099	265-410299-001-0099	Passed	EXIT PASSAGE N88	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

0100	265-410299-001-0100	Failed	EXIT PASSAGE N88	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Critical

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC8
Leaf B	90 mins	N/A	FC8

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1
Floor: B

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0101	265-410299-001-0101	Failed	STAIR #4 N82	Ivan Albert	9/06/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Critical

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC8
Leaf B	90 mins	N/A	FC8

0102	265-410299-001-0102	Passed	STAIR #4 N82	Ivan Albert	9/06/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

0103	265-410299-001-0103	Passed	ELECTRICAL CL N83	Ivan Albert	8/27/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0104	265-410299-001-0104	Passed	ELECTRICAL N78	Ivan Albert	8/27/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

0105	265-410299-001-0105	Failed	EXIT PASSAGE N88	Ivan Albert	9/06/2024
Single	Hollow Metal	44" (3'8") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC10

0106	265-410299-001-0106	Failed	EXIT PASSAGE N88	Kevin Sheehan	9/18/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	Critical

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	Label Missing	N/A	FC5, FC13.D, FC13.F
Leaf B	Label Missing	N/A	FC5, FC13.D, FC13.F

0107	265-410299-001-0107	Passed	STAIR #3 W53	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0108	265-410299-001-0108	Passed	ELECTRICAL CL W54	Ivan Albert	8/27/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

Building: DVA-1 EAST

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 EAST
Floor: 1

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0145	265-410299-001-0145	Passed	STAIR 5 SE091A	Ivan Albert	8/27/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

Floor: B

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0147	265-410299-001-0147	Passed	STAIR 5 SE001B	Ivan Albert	8/27/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

Floor: LL

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0144	265-410299-001-0144	Passed	STAIR 6 SE002A	Ivan Albert	8/27/2024
Single	Hollow Metal	44" (3'8") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

Building: DVA-15
Floor: 1

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0007	265-410299-001-0007	Passed	STAIR #1 S1A	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	44" (3'8") x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

0008	265-410299-001-0008	Passed	ELEV PUMP R D102	Ivan Albert	8/26/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0009	265-410299-001-0009	Failed	CLOSET 104A	Ivan Albert	8/27/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	Label Missing	N/A	FC13.D, FC15

0010	265-410299-001-0010	Failed	STAIR #2 S2A	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	Immediate

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15
Floor: 1

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0010	265-410299-001-0010	Passed	STAIR #2 S2A	Ivan Albert	9/06/2024
Single	Hollow Metal	44" (3'8") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0011	265-410299-001-0011	Failed	STAIR #3 S3A	Ivan Albert	9/06/2024
Pair	Hollow Metal	44" (3'8") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC10
Leaf B	90 mins	N/A	FC10

0012	265-410299-001-0012	Passed	CORRIDOR C14	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	42" (3'6") x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

Floor: 2

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0004	265-410299-001-0004	Failed	STAIR S2A	Kevin Sheehan	9/16/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC5

0005	265-410299-001-0005	Failed	ELECTRICAL D251	Ivan Albert	9/06/2024
Single	Wood	36" x 84"	Hollow Metal Not Filled	1-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	45 mins	N/A	FC1

0006	265-410299-001-0006	Passed	CIRC CORRIDOR C201	Kevin Sheehan	9/16/2024
Double Egress	Hollow Metal	48" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

Floor: B

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0014	265-410299-001-0014	Passed	STAIR #1 S1	Ivan Albert	8/26/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15
Floor: B

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0015	265-410299-001-0015	Failed	ELECTRICAL D02	Ivan Albert	9/06/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	1-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC10

0016	265-410299-001-0016	Passed	ELECTRICAL D02	Kevin Sheehan	9/16/2024
Single	Wood	36" x 84"	Hollow Metal Not Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

0017	265-410299-001-0017	Passed	CLOSET D04A	Ivan Albert	9/06/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	180 mins	N/A	N/A

0018	265-410299-001-0018	Failed	STAIR #2 S2	Ivan Albert	9/06/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC10

0020	265-410299-001-0020	Failed	STAIR #3 S3	Ivan Albert	9/06/2024
Pair	Hollow Metal	42" (3'6") x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC10
Leaf B	90 mins	N/A	FC10

0022	265-410299-001-0022	Failed	CORRIDOR C 5	Kevin Sheehan	9/16/2024
Double Egress	Hollow Metal	42" (3'6") x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC5
Leaf B	90 mins	N/A	FC5

Building: DVA-18
Floor: 1

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0001	265-410299-001-0001	Passed	WAITING RM 103	Kevin Sheehan	9/16/2024
Double Egress	Wood	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A
Leaf B	90 mins	N/A	N/A

0002	265-410299-001-0002	Failed	CORRIDOR 103A	Ivan Albert	9/06/2024
Double Egress	Wood	48" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	Critical

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	FC4, FC6, FC8
Leaf B	90 mins	N/A	FC4, FC6, FC8

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Door Inspection Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-18
Floor: 1

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0003	265-410299-001-0003	Passed	ELECTRICAL 106A	Kevin Sheehan	9/16/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

Building: DVA-1E
Floor: 1

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0143	265-410299-001-0143	Passed	STAIR	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Not Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	90 mins	N/A	N/A

Floor: B

Opening Door Type	Barcode Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
0146	265-410299-001-0146	Passed	STAIR	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x 84"	Hollow Metal Not Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label	Failed Fire Criteria
Leaf A	60 mins	N/A	N/A

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0072

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0072	Yes / No	Passed	STAIR E 137	Ivan Albert	9/06/2024
Single	Hollow Metal	46" (3'10") x 84"	Hollow Metal Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Hardware	Yes	Yes

FC4 - Repaired Deficiency



Push



Pull

FC4 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0073

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0073	Yes / No	Passed	WAITING RM E129	Ivan Albert	9/06/2024
Pair	Wood	44" (3'8") x	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Hardware	Yes	Yes

FC4 - Repaired Deficiency

Push



Pull

FC4 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0074

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0074	Yes / No	Passed	STAIR #1 E111	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0075

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0075	Yes / No	Passed	ELECTRICAL CL E110	Ivan Albert	8/27/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0077

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0077	Yes / No	Passed	ELECTRICAL CL N145	Kevin Sheehan	9/18/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0077

Barcode	Fire / Smoke	P/F	Area	Inspector	Date
Door Type	**Door Material**	**Door Size**	**Frame Material**	**Barrier Type**	**Priority**

Push

Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0078

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0078	Yes / No	Passed	CORRIDOR N147A	Ivan Albert	8/27/2024
Double Egress	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0079

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0079	Yes / No	Passed	STAIR #4 N126	Kevin Sheehan	9/16/2024
Single	Hollow Metal	32" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0080

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0080	Yes / No	Passed	STAIR #3 W145	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency



Push

Pull

FC4 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0081

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0081	Yes / No	Passed	SPRINKLER CONTROL	Ivan Albert	8/27/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0082

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0082	Yes / No	Passed	ELECTRICAL CL W146	Ivan Albert	8/27/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0083

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0083	Yes / No	Failed	VESTIBULE NW141	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	Critical

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC6	Closer leaking fluid		Hardware	No	No
FC6	Closer leaking fluid		Hardware	No	No

Push

Pull



FC6 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0084

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0084	Yes / No	Passed	VESTIBULE NW141	Kevin Sheehan	9/16/2024
Pair	Wood	46" (3'10") x 90"	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Push

Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0085

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0085	Yes / No	Passed	EMER ELECTR SW103	Ivan Albert	8/27/2024
Single	Wood	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0086

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0086	Yes / No	Passed	ELECTRICAL CL SW102	Ivan Albert	8/27/2024
Single	Wood	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 1 Opening: 0087

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0087	Yes / No	Failed	OFFICE NW101	Ivan Albert	9/06/2024
Single	Wood	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Missing closer		Hardware	No	No

Push



FC4 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 2 Opening: 0063

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0063	Yes / No	Passed	STAIR #1 E209	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency



Push

Pull

FC4 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 2 Opening: 0064

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0064	Yes / No	Passed	ELECTIRCAL CL E210	Kevin Sheehan	9/16/2024
Single	Hollow Metal	30 x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 2 Opening: 0065

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0065	Yes / No	Passed	STAIR #2 N286	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency

Push



Pull



FC4 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 2 Opening: 0066

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0066	Yes / No	Passed	ELECTRICAL CL N285	Kevin Sheehan	9/18/2024
Single	Hollow Metal	30 x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 2 Opening: 0067

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0067	Yes / No	Passed	STAIR #4 N273	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency



Push

Pull

FC4 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 2 Opening: 0068

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0068	Yes / No	Passed	ELECTRICAL CL N 272	Kevin Sheehan	9/16/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 2 Opening: 0069

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0069	Yes / No	Passed	ELECTRICAL CL W255	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 2 Opening: 0070

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0070	Yes / No	Passed	STAIR #3 W246	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency



Push

Pull

FC4 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 2 Opening: 0071

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0071	Yes / No	Passed	ELECTRICAL CL W247	Kevin Sheehan	9/16/2024
Single	Hollow Metal	30" x 80"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 2 Opening: 0148

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0148	Yes / No	Passed	ELECTRICAL W154A	Ivan Albert	8/27/2024
Pair	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Push

Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 2 Opening: 0149

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0149	Yes / No	Passed	CHAPEL N267	Ivan Albert	9/06/2024
Single	Wood	42" (3'6") x	Hollow Metal Not Filled	1-Hour Smoke Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	20 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC1	Missing silencer / mute		Frame	Yes	Yes
FC4	Strike plate missing fastener		Hardware	Yes	Yes
FC5	WD/PLAM top edge clearance > 1/8"		Top	Yes	Yes

FC1 - Repaired Deficiency

FC4 - Repaired Deficiency



Push

Deficiency

FC1 - Deficiency

FC4 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 2 Opening: 0149

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
FC5 - Deficiency 					

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 3 Opening: 0053

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0053	Yes / No	Passed	STAIR #1 E316	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency



Push



Pull



FC4 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 3 Opening: 0054

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0054	Yes / No	Passed	ELECTRICAL CL E315	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 3 Opening: 0055

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0055	Yes / No	Passed	ELECTRICAL CL N389	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Pull



Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 3 Opening: 0056

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0056	Yes / No	Passed	STAIR - N390	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency



Push



Pull



FC4 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 3 Opening: 0057

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0057	Yes / No	Passed	STAIR #4 N375	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency

Push



Pull

FC4 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 3 Opening: 0058

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0058	Yes / No	Passed	ELECTRICAL CL N376	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 3 Opening: 0059

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0059	Yes / No	Passed	ELECTRICAL C W357A	Ivan Albert	8/26/2024
Pair	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 3 Opening: 0061

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0061	Yes / No	Passed	STAIR #3 W349	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency



Push

Pull



FC4 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 3 Opening: 0062

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0062	Yes / No	Passed	ELECTRICAL CL W350	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 4 Opening: 0044

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0044	Yes / No	Passed	STAIR #1 E415	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency



Push

Pull

FC4 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 4 Opening: 0045

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0045	Yes / No	Passed	ELECTRICAL CL E414	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 4 Opening: 0046

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0046	Yes / No	Passed	STAIR #2 N498	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency



Push

Pull



FC4 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 4 Opening: 0047

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0047	Yes / No	Passed	ELECTRICAL CL N497	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 4 Opening: 0048

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0048	Yes / No	Passed	STAIR #4 N481	Ivan Albert	9/06/2024
Single	Hollow Metal	44" (3'8") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Hardware	Yes	Yes

FC4 - Repaired Deficiency

Push

Pull



FC4 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 4 Opening: 0049

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0049	Yes / No	Passed	ELECTRICAL CL N480A	Ivan Albert	9/06/2024
Single	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC8	Latch obstructed (tape or other means)		Hardware	Yes	Yes

FC8 - Repaired Deficiency

Push



FC8 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 4 Opening: 0050

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0050	Yes / No	Passed	ELECTRICAL CL W453	Ivan Albert	8/26/2024
Pair	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Push

Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 4 Opening: 0051

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0051	Yes / No	Passed	STAIR #3 W446	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 4 Opening: 0052

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0052	Yes / No	Passed	ELECTRICAL CL W447	Kevin Sheehan	9/16/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 5 Opening: 0033

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0033	Yes / No	Passed	STAIR #1 E515	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 5 Opening: 0034

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0034	Yes / No	Passed	ELECTRICAL CL E514	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 5 Opening: 0035

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0035	Yes / No	Passed	STAIR #2 N578	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes
FC5	WD/PLAM strike edge clearance > 1/8" Bottom clearance for HM and WD/PLAM > 3/4"		Strike Edge	Yes	Yes

Repaired Deficiency

FC4 - Repaired Deficiency



Push

Pull



FC4 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 5 Opening: 0036

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0036	Yes / No	Passed	ELECTRICAL CL N577	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 5 Opening: 0037

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0037	Yes / No	Passed	STAIR N565	Kevin Sheehan	9/18/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency



Push



Pull

FC4 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 5 Opening: 0038

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0038	Yes / No	Passed	CORRIDOR N569A	Ivan Albert	9/06/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Hardware	Yes	Yes

FC4 - Repaired Deficiency



Push



Pull

FC4 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 5 Opening: 0039

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0039	Yes / No	Failed	MECHANICAL N566	Kevin Sheehan	9/16/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC13.F	Missing / illegible frame label		Frame	No	No

Push

Pull

FC13.F - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 5 Opening: 0040

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0040	Yes / No	Passed	MECHANICAL N567	Ivan Albert	8/26/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 5 Opening: 0041

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0041	Yes / No	Passed	ELECTRICAL CL W566	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Push



Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 5 Opening: 0042

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0042	Yes / No	Passed	ELECTRICAL CL W549	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 5 Opening: 0043

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0043	Yes / No	Passed	STAIR #3 W548	Ivan Albert	9/06/2024
Single	Hollow Metal	44" (3'8") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC5	HM top edge clearance > 3/16"		Top	Yes	Yes

FC5 - Repaired Deficiency



Push

Pull

FC5 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 6 Opening: 0025

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0025	Yes / No	Passed	STAIR #1 E614	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Push

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 6 Opening: 0026

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0026	Yes / No	Passed	ELECTRICAL CL E613	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 6 Opening: 0027

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0027	Yes / No	Passed	ELECTRICAL CL N661	Ivan Albert	8/26/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 6 Opening: 0028

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0028	Yes / No	Passed	STAIR #2 N662	Kevin Sheehan	9/16/2024
Single	Hollow Metal	44" (3'8") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency



Push

Pull

FC4 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 6 Opening: 0029

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0029	Yes / No	Passed	STAIR N653	Ivan Albert	8/26/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 6 Opening: 0030

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0030	Yes / No	Passed	ELECTRICAL CL W645	Ivan Albert	9/06/2024
Pair	Hollow Metal	24" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC1	Missing silencer / mute		Frame	Yes	Yes

FC1 - Repaired Deficiency

Push



Pull

FC1 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 6 Opening: 0031

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0031	Yes / No	Failed	STAIR #3 W638	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	Essential

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes
FC12	Signage > 5%		Size	No	No

FC4 - Repaired Deficiency



Push

Pull

FC12 - Deficiency

FC4 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 6 Opening: 0031

Barcode	Fire / Smoke	P/F	Area	Inspector	Date
Door Type	Door Material	Door Size	Frame Material	Barrier Type	Priority

FC4 - Repaired Deficiency



Push

Pull

FC12 - Deficiency

FC4 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: 7 Opening: 0024

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0024	Yes / No	Passed	STAIR #2 E703	Ivan Albert	8/26/2024
Single	Hollow Metal	44" (3'8") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC9	Door impeded / obstructed by object, non compliant hardware or device		Hardware	Yes	Yes

Push

Pull



FC9 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0091

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0091	Yes / No	Passed	STAIR #1 E07	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Frame	Yes	Yes

FC4 - Repaired Deficiency

Push



Pull

FC4 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0092

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0092	Yes / No	Passed	ELECTRICAL CL E06	Ivan Albert	9/06/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC1	Missing silencer / mute		Frame	Yes	Yes

FC1 - Repaired Deficiency

Push

Pull



FC1 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0094

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0094	Yes / No	Failed	STAIR #2 N100	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC1	Missing hardware leaving hole in frame / door		Frame	No	No
FC4	Strike plate missing fastener		Hardware	Yes	Yes
FC5	HM top edge clearance > 3/16"		Top	No	No

FC4 - Repaired Deficiency



Push



Pull

FC1 - Deficiency



FC4 - Deficiency

FC5 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0095

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0095	Yes / No	Passed	ELECTRICAL CL N99	Ivan Albert	8/27/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0096

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0096	Yes / No	Failed	STAIR #2 N100	Ivan Albert	9/06/2024
Single	Hollow Metal	48" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Critical

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC1	Missing hardware leaving hole in frame / door		Door	Yes	Yes
FC8	Lock/latch/fire exit hardware is not fire rated		Hardware	No	No

FC1 - Repaired Deficiency

FC1 - Repaired Deficiency

Push

Pull



FC1 - Deficiency

FC8 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0097

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0097	Yes / No	Passed	ROOM NE103	Ivan Albert	8/27/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0098

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0098	Yes / No	Passed	CORRIDOR N89	Kevin Sheehan	9/18/2024
Double Egress	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0099

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0099	Yes / No	Passed	EXIT PASSAGE N88	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0100

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0100	Yes / No	Failed	EXIT PASSAGE N88	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Critical

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC8	Lock/latch/fire exit hardware is missing - specify item		Hardware, Hardware	No	No

Push



Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0101

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0101	Yes / No	Failed	STAIR #4 N82	Ivan Albert	9/06/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Critical

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC8	Door rubs or binds preventing latch engagement		Hardware	No	No

Push



Pull



FC8 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0102

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0102	Yes / No	Passed	STAIR #4 N82	Ivan Albert	9/06/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC7	Coordinator is not damaged but not working properly		Hardware	Yes	Yes

FC7 - Repaired Deficiency



Push



Pull



FC7 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0103

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0103	Yes / No	Passed	ELECTRICAL CL N83	Ivan Albert	8/27/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0104

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0104	Yes / No	Passed	ELECTRICAL N78	Ivan Albert	8/27/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0105

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0105	Yes / No	Failed	EXIT PASSAGE N88	Ivan Albert	9/06/2024
Single	Hollow Metal	44" (3'8") x	Hollow Metal Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC10	Protection plate on door made of combustible material (e.g. masonite, plywood, plexiglass)		Door	No	No

Push



Pull



FC10 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0106

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0106	Yes / No	Failed	EXIT PASSAGE N88	Kevin Sheehan	9/18/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	Critical

Leaf	Fire Rating	Smoke Label
Leaf A	Label Missing	N/A
Leaf B	Label Missing	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC5	Bottom clearance for HM and WD/PLAM > 3/4"		Bottom	No	No
FC13.D	Missing / illegible door label (double-check top of door)		Door	No	No
FC13.F	Missing / illegible frame label		Frame	No	No

Push



Pull

FC13.D - Deficiency



FC13.F - Deficiency

FC5 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0107

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0107	Yes / No	Passed	STAIR #3 W53	Kevin Sheehan	9/18/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 Floor: B Opening: 0108

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0108	Yes / No	Passed	ELECTRICAL CL W54	Ivan Albert	8/27/2024
Single	Hollow Metal	30" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 EAST Floor: 1 Opening: 0145

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0145	Yes / No	Passed	STAIR 5 SE091A	Ivan Albert	8/27/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 EAST Floor: B Opening: 0147

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0147	Yes / No	Passed	STAIR 5 SE001B	Ivan Albert	8/27/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1 EAST Floor: LL Opening: 0144

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0144	Yes / No	Passed	STAIR 6 SE002A	Ivan Albert	8/27/2024
Single	Hollow Metal	44" (3'8") x	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: 1 Opening: 0007

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0007	Yes / No	Passed	STAIR #1 S1A	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	44" (3'8") x	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: 1 Opening: 0008

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0008	Yes / No	Passed	ELEV PUMP R D102	Ivan Albert	8/26/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: 1 Opening: 0009

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0009	Yes / No	Failed	CLOSET 104A	Ivan Albert	8/27/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	Label Missing	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC13.D	Missing / illegible door label (double-check top of door)		Door	Yes	Yes
FC15	No louver or transfer grille installed in door		Hardware	No	No

Pull

FC15 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: 1 Opening: 0010

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0010	Yes / No	Failed	STAIR #2 S2A	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC10	Protection plate on door made of combustible material (e.g. masonite, plywood, plexiglass)		Door	No	No

Push



Pull

FC10 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: 1 Opening: 0010

Barcode	Fire / Smoke	P/F	Area	Inspector	Date
Door Type	**Door Material**	**Door Size**	**Frame Material**	**Barrier Type**	**Priority**

Push



Pull

FC10 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: 1 Opening: 0011

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0011	Yes / No	Failed	STAIR #3 S3A	Ivan Albert	9/06/2024
Pair	Hollow Metal	44" (3'8") x	Hollow Metal Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC10	Protection plate on door made of combustible material (e.g. masonite, plywood, plexiglass)		Door	No	No

Push



Pull

FC10 - Deficiency



FC10 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: 1 Opening: 0012

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0012	Yes / No	Passed	CORRIDOR C14	Kevin Sheehan	9/16/2024
Pair	Hollow Metal	42" (3'6") x	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Push



Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: 2 Opening: 0004

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0004	Yes / No	Failed	STAIR S2A	Kevin Sheehan	9/16/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC5	Bottom clearance for HM and WD/PLAM > 3/4" HM top edge clearance > 3/16"		Top, Bottom	No	No

Push

Pull



FC5 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: 2 Opening: 0005

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0005	Yes / No	Failed	ELECTRICAL D251	Ivan Albert	9/06/2024
Single	Wood	36" x 84"	Hollow Metal Not Filled	1-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label
Leaf A	45 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC1	Unused fastener hole in frame / door		Door	No	No

Push

Pull



FC1 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: 2 Opening: 0006

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0006	Yes / No	Passed	CIRC CORRIDOR C201	Kevin Sheehan	9/16/2024
Double Egress	Hollow Metal	48" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Push



Push



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: B Opening: 0014

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0014	Yes / No	Passed	STAIR #1 S1	Ivan Albert	8/26/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: B Opening: 0015

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0015	Yes / No	Failed	ELECTRICAL D02	Ivan Albert	9/06/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	1-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC10	Protection plate on door made of combustible material (e.g. masonite, plywood, plexiglass)		Door	No	No

Push

Pull



FC10 - Deficiency

FC10 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: B Opening: 0016

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0016	Yes / No	Passed	ELECTRICAL D02	Kevin Sheehan	9/16/2024
Single	Wood	36" x 84"	Hollow Metal Not Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC1	Missing silencer / mute		Frame	Yes	Yes

FC1 - Repaired Deficiency

Push



Pull

FC1 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: B Opening: 0017

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0017	Yes / No	Passed	CLOSET D04A	Ivan Albert	9/06/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	180 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC1	Missing silencer / mute		Frame	Yes	Yes

FC1 - Repaired Deficiency

Push

Pull

FC1 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: B Opening: 0018

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0018	Yes / No	Failed	STAIR #2 S2	Ivan Albert	9/06/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC10	Protection plate on door made of combustible material (e.g. masonite, plywood, plexiglass)		Door	No	No

Push

Pull



FC10 - Deficiency

FC10 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: B Opening: 0020

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0020	Yes / No	Failed	STAIR #3 S3	Ivan Albert	9/06/2024
Pair	Hollow Metal	42" (3'6") x	Hollow Metal Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC10	Protection plate on door made of combustible material (e.g. masonite, plywood, plexiglass)		Door	No	No

Push



Pull

FC10 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-15 Floor: B Opening: 0022

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0022	Yes / No	Failed	CORRIDOR C 5	Kevin Sheehan	9/16/2024
Double Egress	Hollow Metal	42" (3'6") x	Hollow Metal Not Filled	2-Hour Fire Barrier	Immediate

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC5	Bottom clearance for HM and WD/PLAM > 3/4"		Bottom	No	No

Push

Pull

FC5 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-18 Floor: 1 Opening: 0001

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0001	Yes / No	Passed	WAITING RM 103	Kevin Sheehan	9/16/2024
Double Egress	Wood	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC1	Unused hardware leaving hole in the door or frame		Frame	Yes	Yes
FC6	Stack pressure is preventing door closer from operating properly		Hardware	Yes	Yes

FC1 - Repaired Deficiency



FC6 - Repaired Deficiency

Push

Push



FC1 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-18 Floor: 1 Opening: 0002

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0002	Yes / No	Failed	CORRIDOR 103A	Ivan Albert	9/06/2024
Double Egress	Wood	48" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	Critical

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A
Leaf B	90 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC4	Strike plate missing fastener		Hardware	Yes	Yes
FC6	Sweep or other hardware hindering closing		Hardware	Yes	Yes
FC8	Fire exit hardware missing bottom rod without fire pin		Hardware	No	No

FC4 - Repaired Deficiency



FC6 - Repaired Deficiency



FC6 - Repaired Deficiency

Push

Push

FC4 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-18 Floor: 1 Opening: 0002

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority

FC6 - Deficiency

FC8 - Deficiency

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-18 Floor: 1 Opening: 0003

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0003	Yes / No	Passed	ELECTRICAL 106A	Kevin Sheehan	9/16/2024
Single	Hollow Metal	36" x 84"	Hollow Metal Not Filled	2-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push

Pull



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1E Floor: 1 Opening: 0143

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0143	Yes / No	Passed	STAIR	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Not Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	90 mins	N/A

Push



Pull

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

Initial Annual Fire & Smoke Inspection Door Details

Name Manchester Va
Address 718 Smyth Road Manchester, NH 03104
Inspection Dates 8/26/2024 To 9/18/2024 **Project #** 484898 **Inspection No.** SLS484561

Building: DVA-1E Floor: B Opening: 0146

Barcode Door Type	Fire / Smoke Door Material	P/F Door Size	Area Frame Material	Inspector Barrier Type	Date Priority
265-410299-001-0146	Yes / No	Passed	STAIR	Kevin Sheehan	9/16/2024
Single	Hollow Metal	42" (3'6") x	Hollow Metal Not Filled	1-Hour Fire Barrier	N/A

Leaf	Fire Rating	Smoke Label
Leaf A	60 mins	N/A

Criteria	Failed Notes	General Notes	Components	Repaired	Compliant Repaired
FC5	HM top edge clearance > 3/16"		Top	Yes	Yes

FC5 - Repaired Deficiency

Push

Pull

FC5 - Deficiency



This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.

--- End of Report ---

Faletti Construction LLC
Manchester Va
718 Smyth Road
Manchester, NH 03104

Inspection No.:	SLS484561
Code Edition:	NFPA 80 - 2010 for Healthcare
Inspection Initiated:	August 26 2024

DHPACE®
COMPLIANCE SERVICES
Inspections • Labeling • Training • Consulting

If the report indicates that deficiencies were found (and were not repaired on-site), please refer to corresponding proposal.
This comprehensive FireCheck® inspection report is based on NFPA 80 (fire) and NFPA 105 (smoke) requirements. This report applies only to door list provided by the Customer.

Code Interpretation Disclaimer: All information provided by DH Pace Inc. represents our interpretation regarding the intent of the standard(s) and/or code(s) applicable to the issue being addressed. By law, the Authority Having Jurisdiction (AHJ) is the only entity with the legal standing and discretionary authority to make a definitive ruling on these matters. As such, DH Pace disclaims any consequential damages that may arise from the use of the information provided, recommendation made, or opinions expressed on this matter.

This document was developed by and is the Exclusive property of DH Pace Company, Inc. Any unauthorized use, reproduction or duplication, in whole or in part, is expressly prohibited. © 2022 DH Pace Company, Inc.