MANCHESTER VA MEDICAL CENTER
718 Smyth Road
Manchester, NH 03104

April 2023 - Inspection Date(s) 4/20/2023

Fire Door PM Report

Order No. 36C24118C0047

PO 608C38066

PREPARED BY:

EOC SOLUTIONS

PO Box 337, Perkasie, PA 18944
PHONE: (215) 258-3910
www.eocsolutions.com

Fire Door Report Summary

Total number of doors	113
Passing Doors	109
Repaired/Passed Doors	0
Not Repaired Doors	4

Inspection Details

Total number of doors	113
Swinging Doors	113
Passed Doors	109
Failed Doors	4

Repair Details

Doors Repaired/Passed	0
Doors Not Repaired	4

007082Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Confined Space inside stair 3	Door Rating:	3 Hour
		Floor:	Basement	Frame Rating:	3 Hour

Deficiency Detail

Door passed inspection

007083Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Confined Space inside stair 1	Door Rating:	3 Hour
		Floor:	Basement	Frame Rating:	3 Hour

Deficiency Detail

Door passed inspection

007087Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Confined Space inside stair 2	Door Rating:	3 Hour
		Floor:	Basement	Frame Rating:	3 Hour

Deficiency Detail

Door passed inspection

007096Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double doors to Stair 4	Door Rating:	90 Minute
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007097Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Stair 4	Door Rating:	3 Hour
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007098Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 4	Door Rating:	3 Hour
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007099Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Stair 4	Door Rating:	3 Hour
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007100Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Stair 4	Door Rating:	90 Minute
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007101Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	N84 Storage Room	Door Rating:	90 Minute
		Floor:	Basement	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007104Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double Doors by Stair 4	Door Rating:	90 Minute
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007105Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double Doors by Stair 4	Door Rating:	90 Minute
		Floor:	Basement	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007108Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Cross Corridor to Seacoast Entry	Door Rating:	90 Minute
		Floor:	Basement	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007109Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Cross Corridor to Seacoast Entry	Door Rating:	90 Minute
		Floor:	Basement	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007113Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Distribution Vault NE103	Door Rating:	90 Minute
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007114Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 2	Door Rating:	3 Hour
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007115Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 2	Door Rating:	3 Hour
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007116Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 1	Door Rating:	90 Minute
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007117Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 1	Door Rating:	90 Minute
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007124Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 3	Door Rating:	3 Hour
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007125Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 3	Door Rating:	3 Hour
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007181Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Pharmacy Storage Room	Door Rating:	90 Minute
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007182Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Pharmacy Storage Room	Door Rating:	90 Minute
		Floor:	Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007064Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 4	Door Rating:	3 Hour
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007065Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Cross Corridor to Community Living Center	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007066Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Cross Corridor to Community Living Center	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007067Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Shaft by Stair 2	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007069Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 1	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007074Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 3	Door Rating:	3 Hour
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007075Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Shaft inside stair 3	Door Rating:	3 Hour
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007076Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 3 Electric shaft	Door Rating:	3 Hour
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007077Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 3	Door Rating:	3 Hour
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007078Z — FAIL

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double Doors by Stair 3	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door does not latch - NFPA 80-2010 5.2.4.2 (8); NFPA 101-2012 18.3.6.3.5, 19.3.6.3.5 (1)
Electrical controlled, needs adjusted by certified tech

Phase 1	Randy Berg	4/20/2023	Deficiency not repaired: client will address. Per Sean, client will address

007079Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double Doors by Stair 3	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007080Z — FAIL

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Cross Corridor to Primary Care	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	Label present; no rating specified

Deficiency Detail

Excessive clearance - NFPA 80-2010 5.2.4.2 (5), NFPA 80-2010 6.3.1.7

Center gap

Phase 1	Randy Berg	4/20/2023	Deficiency not repaired: client will address. Per Sean, client will address	

Panic hardware applied to fire rated assembly - NFPA 101-2012 7.2.1.7.2; NFPA 80-2010 6.4.4.2.3

Phase 1	Randy Berg	4/20/2023	Deficiency not repaired: client will address. Per Sean, client will address	

007081Z — FAIL

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Cross Corridor to Primary Care	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	Label present; no rating specified

Deficiency Detail

Panic hardware applied to fire rated assembly - NFPA 101-2012 7.2.1.7.2; NFPA 80-2010 6.4.4.2.3

Phase 1	Randy Berg	4/20/2023	Deficiency not repaired: client will address. Per Sean, client will address	

007084Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Cross Corridor to Sunapee Waiting Room	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007085Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Cross Corridor to Sunapee Waiting Room	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007089Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Electrical Closet SW102	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007090Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Electrical Closet SW103	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007173Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 1	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007174Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Pharmacy back door	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

10234143 — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Electrical Room across from Staff Elevators	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

10234144 — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Electrical Room across from Staff Elevators	Door Rating:	90 Minute
		Floor:	1	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

282634 PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 2	Door Rating:	3 Hour
		Floor:	1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007052Z PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 3	Door Rating:	3 Hour
		Floor:	2	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007053Z PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 3	Door Rating:	3 Hour
		Floor:	2	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007054Z PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Double doors to Electrical Room	Door Rating:	90 Minute
		Floor:	2	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007055Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Double doors to Electrical Room	Door Rating:	90 Minute
		Floor:	2	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007056Z — FAIL

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 1	Door Rating:	90 Minute
		Floor:	2	Frame Rating:	90 Minute

Deficiency Detail

Exit device missing label - NFPA 80-2010 6.4.4.1, 6.4.4.2.3

Phase 1	Randy Berg	4/20/2023	Deficiency not repaired: exit hardware should be evaluated for relabeling	

007057Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 1 Electrical Shaft	Door Rating:	90 Minute
		Floor:	2	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007058Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 2	Door Rating:	3 Hour
		Floor:	2	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007059Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 2	Door Rating:	3 Hour
		Floor:	2	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007060Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Cross Corridor to Specialty Clinics	Door Rating:	90 Minute
		Floor:	2	Frame Rating:	3 Hour

Deficiency Detail

Door passed inspection

007061Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Cross Corridor to Specialty Clinics	Door Rating:	90 Minute
		Floor:	2	Frame Rating:	3 Hour

Deficiency Detail

Door passed inspection

007062Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 4	Door Rating:	3 Hour
		Floor:	2	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007063Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 4	Door Rating:	3 Hour
		Floor:	2	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007042Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 1	Door Rating:	90 Minute
		Floor:	3	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007043Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 1 Electrical Shaft	Door Rating:	90 Minute
		Floor:	3	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007044Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Electrical Room across from Staff Elevators	Door Rating:	90 Minute
		Floor:	3	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007045Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Electrical Room across from Staff Elevators	Door Rating:	90 Minute
		Floor:	3	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007046Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 3	Door Rating:	3 Hour
		Floor:	3	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007047Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 3	Door Rating:	3 Hour
		Floor:	3	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007048Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 2	Door Rating:	3 Hour
		Floor:	3	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007049Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 2	Door Rating:	3 Hour
		Floor:	3	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007050Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 4	Door Rating:	3 Hour
		Floor:	3	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007051Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 4	Door Rating:	3 Hour
		Floor:	3	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007024Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 3	Door Rating:	3 Hour
		Floor:	4	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007025Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 3	Door Rating:	3 Hour
		Floor:	4	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007028Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 4 Electrical Shaft	Door Rating:	90 Minute
		Floor:	4	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007029Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 4	Door Rating:	90 Minute
		Floor:	4	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007032Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 2	Door Rating:	3 Hour
		Floor:	4	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007033Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 2	Door Rating:	3 Hour
		Floor:	4	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007040Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 1	Door Rating:	90 Minute
		Floor:	4	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007041Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 1 Electrical Shaft	Door Rating:	90 Minute
		Floor:	4	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007183Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Double doors to Electrical Closet W453	Door Rating:	45 Minute
		Floor:	4	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007184Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Double doors to Electrical Closet W453	Door Rating:	45 Minute
		Floor:	4	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007012Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Mechanical Room N567	Door Rating:	3 Hour
		Floor:	5	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007013Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Mechanical Room N566	Door Rating:	90 Minute
		Floor:	5	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007014Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair N569	Door Rating:	3 Hour
		Floor:	5	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007015Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 2	Door Rating:	3 Hour
		Floor:	5	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007016Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 2	Door Rating:	3 Hour
		Floor:	5	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007017Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 1	Door Rating:	90 Minute
		Floor:	5	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007018Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 1	Door Rating:	90 Minute
		Floor:	5	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007019Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Electrical Room across from Staff Elevator's	Door Rating:	90 Minute
		Floor:	5	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007020Z — PASS



Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Electrical Room across from Staff Elevator's	Door Rating:	90 Minute
		Floor:	5	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007021Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 3	Door Rating:	3 Hour
		Floor:	5	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007022Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside Stair 3	Door Rating:	3 Hour
		Floor:	5	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007003Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Shaft inside Stair 2	Door Rating:	3 Hour
		Floor:	6	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007004Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 2	Door Rating:	3 Hour
		Floor:	6	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007005Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair N653	Door Rating:	3 Hour
		Floor:	6	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007006Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 1	Door Rating:	90 Minute
		Floor:	6	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007007Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Shaft E613 in stair 1	Door Rating:	90 Minute
		Floor:	6	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007008Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Electrical Room across from Staff Elevator's	Door Rating:	90 Minute
		Floor:	6	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007009Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Electrical Room across from Staff Elevator's	Door Rating:	90 Minute
		Floor:	6	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007010Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 3	Door Rating:	3 Hour
		Floor:	6	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007011Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Shaft inside stair 3	Door Rating:	3 Hour
		Floor:	6	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007002Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Mechanical Room in Stair 2	Door Rating:	3 Hour
		Floor:	7	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007161Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Electrical Room D02	Door Rating:	90 Minute
		Floor:	Building 15 Basement	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007162Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 1	Door Rating:	90 Minute
		Floor:	Building 15 Basement	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007163Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Electrical Room D02	Door Rating:	90 Minute
		Floor:	Building 15 Basement	Frame Rating:	45 Minute

Deficiency Detail

Door passed inspection

007168Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair 2	Door Rating:	90 Minute
		Floor:	Building 15 Basement	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007171Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Stair 3	Door Rating:	90 Minute
		Floor:	Building 15 Basement	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007172Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double Doors to Stair 3	Door Rating:	90 Minute
		Floor:	Building 15 Basement	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007137Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Electrical Room across from Stair 1	Door Rating:	90 Minute
		Floor:	Building 15 Floor 1	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007138Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double doors to Stair 1	Door Rating:	90 Minute
		Floor:	Building 15 Floor 1	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007139Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double doors to Stair 1	Door Rating:	90 Minute
		Floor:	Building 15 Floor 1	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007155Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double doors to Stair 2	Door Rating:	90 Minute
		Floor:	Building 15 Floor 1	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007156Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double doors to Stair 2	Door Rating:	90 Minute
		Floor:	Building 15 Floor 1	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007159Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double doors to Stair 3	Door Rating:	90 Minute
		Floor:	Building 15 Floor 1	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007160Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Double doors to Stair 3	Door Rating:	90 Minute
		Floor:	Building 15 Floor 1	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection

007129Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	1 Hour
Inspection Date:	4/20/2023	Location:	Electrical Room D251	Door Rating:	45 Minute
		Floor:	Building 15 Floor 2	Frame Rating:	90 Minute

Deficiency Detail

Door passed inspection

007130Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Stair S2A	Door Rating:	90 Minute
		Floor:	Building 15 Floor 2	Frame Rating:	3 Hour

Deficiency Detail

Door passed inspection

007128Z — PASS

Inspector:	Randy Berg	Building:	Main	Wall Rating:	2 Hour
Inspection Date:	4/20/2023	Location:	Electrical Room 106A	Door Rating:	90 Minute
		Floor:	First Floor Plan	Frame Rating:	Label present; no rating specified

Deficiency Detail

Door passed inspection


FIRE PROTECTION FEATURES
LIFE SAFETY PLAN
LEGEND
FIRE BARRIER - (2 HR)
FIRE BARRIER - (1 HR)
SMOKE PARTITION
EXIT
OBSOLETE LINEN CHUTE
HAZARDOUS AREA
BASEMENT
007182Z
007181Z
007098Z
007100Z
007101Z
007096Z
007099Z
007097Z
007105Z
007104Z
007108Z
007109Z
007113Z
007115Z
007087Z
007114Z
007082Z
007125Z
007124Z
007083Z
007117Z
007116Z
MATCHLINE A
MATCHLINE B
(SHEET 15 OF 19)
BUILDING 1
Drawing Title
BASEMENT PLAN
Project Title
FLOOR PLANS
Project Number
XX
Building Number
BUILDING #1
Approved
U. S. DEPARTMENT OF
VETERANS AFFAIRS
VA MEDICAL CENTER
MANCHESTER, NH 03104
Location
BUILDING #1
Date
FEB 19, 2020
Checked
FMS
Drawn
MTW
Drawing Number
A-100
Dwg. 01 of 20
Office of
Construction
and Facilities
Management



Drawing Title	Project Title	Project Number	Office of Construction and Facilities Management
FIRST FLOOR PLAN	FLOOR PLANS	XX	
		Building Number: BUILDING #1	
Approved: U. S. DEPARTMENT OF VETERANS AFFAIRS VA MEDICAL CENTER MANCHESTER, NH 03104	Location: BUILDING #1	Drawing Number: A-101	
	Date: FEB 19, 2020 / Checked: FMS / Drawn: MTW	Dwg. 02 of 20	



Drawing Title: SECOND FLOOR PLAN	Project Title: FLOOR PLANS	Project Number: XX	Office of Construction and Facilities Management
Approved: U. S. DEPARTMENT OF VETERANS AFFAIRS VA MEDICAL CENTER MANCHESTER, NH 03104	Location: BUILDING #1	Building Number: BUILDING #1	
	Date: FEB 19, 2020 / Checked: FMS / Drawn: MTW	Drawing Number: A-102	
		Dwg. 03 of 20	



THIRD FLOOR

FIRE PROTECTION FEATURES
LIFE SAFETY PLAN

LEGEND

- FIRE BARRIER - (2 HR)
- FIRE BARRIER - (1 HR)
- SMOKE PARTITION
- EXIT
- OBSOLETE LINEN CHUTE
- HAZARDOUS AREA

Drawing Title: THIRD FLOOR PLAN	Project Title: FLOOR PLANS	Project Number: XX	Office of Construction and Facilities Management
Approved: U. S. DEPARTMENT OF VETERANS AFFAIRS VA MEDICAL CENTER MANCHESTER, NH 03104	Location: BUILDING #1	Building Number: BUILDING #1	
	Date: FEB 19, 2020 / Checked: FMS / Drawn: MTW	Drawing Number: A-103	
		Dwg. 04 of 20	



FOURTH FLOOR

FIRE PROTECTION FEATURES LIFE SAFETY PLAN

LEGEND

- FIRE BARRIER - (2 HR)
- FIRE BARRIER - (1 HR)
- SMOKE PARTITION
- EXIT
- (L) OBSOLETE LINEN CHUTE
- HAZARDOUS AREA

Drawing Title: FOURTH FLOOR PLAN	Project Title: FLOOR PLANS	Project Number: XX	Office of Construction and Facilities Management
Approved: U. S. DEPARTMENT OF VETERANS AFFAIRS VA MEDICAL CENTER MANCHESTER, NH 03104	Location: BUILDING #1	Building Number: BUILDING #1	
	Date: FEB 19, 2020 / Checked: FMS / Drawn: MTW	Drawing Number: A-104	
		Dwg. 05 of 20	



FIFTH FLOOR

FIRE PROTECTION FEATURES LIFE SAFETY PLAN

LEGEND

- FIRE BARRIER - (2 HR)
- FIRE BARRIER - (1 HR)
- SMOKE PARTITION
- EXIT
- OBSOLETE LINEN CHUTE
- HAZARDOUS AREA

Drawing Title: FIFTH FLOOR PLAN	Project Title: FLOOR PLANS	Project Number: XX	Office of Construction and Facilities Management
Approved: U. S. DEPARTMENT OF VETERANS AFFAIRS VA MEDICAL CENTER MANCHESTER, NH 03104	Location: BUILDING #1	Building Number: BUILDING #1	
	Date: FEB 19, 2020 / Checked: FMS / Drawn: MTW	Drawing Number: A-105	
		Dwg. 06 of 20	

FIRE PROTECTION FEATURES
LIFE SAFETY PLAN

LEGEND

- FIRE BARRIER - (2 HR)
- FIRE BARRIER - (1 HR)
- SMOKE PARTITION
- EXIT
- OBSOLETE LINEN CHUTE
- HAZARDOUS AREA

STAIR 200 SF
OFFICE 120 SF
CONFERENCE ROOM 135 SF
OFFICE 147 SF
OFFICE 109 SF
OFFICE 118 SF
CORRIDOR 271 SF
OFFICE 149 SF
TRAINING AND EDUCATION ROOM 480 SF
OFFICE 143 SF
DUMBWAITER CLOSET 4 SF
MALE 161 SF
FIRE CL 3 SF
ELEC CL 13 SF
STAIR NO. 2 196 SF
STORAGE RM 105 SF
STORAGE ROOM 94 SF
ELEVATOR NO. 1
ELEVATOR NO. 2
SERVICE ELEVATOR NO. 3
CORR 221 SF
B.M.S. CL 27 SF
CLOSET 47 SF
OFFICE 132 SF
OFFICE 121 SF
OFFICE 278 SF
PRINT/FILE ROOM 113 SF
ADMIN 134 SF
OFFICE 111 SF
OFFICE 179 SF
STAIR NO. 1
OFFICE 346 SF
TRAINING ROOM 605 SF
OFFICE 185 SF
STAIR NO. 3
OFFICE 140 SF
OFFICE 140 SF
OFFICE 140 SF
OFFICE 120 SF
FILE ROOM 163 SF
ELEC CL 40 SF
FIRE CL 3 SF
UTILITY RM 32 SF
CORRIDOR 636 SF
CORRIDOR 390 SF
TOILET 32 SF
MECH CL 21 SF
STOR CL 20 SF
TOILET 20 SF
CORRIDOR 772 SF
PRINT NOOK 32 SF
FIRE CL 3 SF
FOYER 20SF
OFFICE 144 SF
OFFICE 97 SF
OFFICE 99 SF
OFFICE 150 SF
OFFICE 150 SF
OFFICE 120 SF
FEMALE BATH 165 SF
OFFICE 285 SF
OFFICE 375 SF
OFFICE 68 SF
WAITING ROOM 117 SF
ANTE RM 93 SF
CONFERENCE ROOM 331 SF
OFFICE 145 SF
OFFICE 156 SF
OFFICE 170 SF
OFFICE 165 SF
OFFICE 150 SF
ADMIN 176 SF
TOILET 94 SF
EXAM ROOM 175 SF
EXAM ROOM 155 SF
EXAM ROOM 147 SF
CHASE

SIXTH FLOOR

Drawing Title: SIXTH FLOOR PLAN	Project Title: FLOOR PLANS	Project Number: XX	Office of Construction and Facilities Management
Approved: U. S. DEPARTMENT OF VETERANS AFFAIRS VA MEDICAL CENTER MANCHESTER, NH 03104	Location: BUILDING #1	Building Number: BUILDING #1	
	Date: FEB 19, 2020 / Checked: FMS / Drawn: MTW	Drawing Number: A-106	
		Dwg. 07 of 20	



FLOOR PLAN

Drawing Title: SEVENTH FLOOR PLAN	Project Title: FLOOR PLANS	Project Number: XX	Office of Construction and Facilities Management
Approved: U. S. DEPARTMENT OF VETERANS AFFAIRS VA MEDICAL CENTER MANCHESTER, NH 03104	Location: BUILDING #1	Building Number: BUILDING #1	
	Date: FEB 19, 2020 / Checked: FMS / Drawn: MTW	Drawing Number: A-107	
		Dwg. 8 of 20	

FIRE PROTECTION FEATURES
LIFE SAFETY PLAN

LEGEND

- FIRE BARRIER - (2 HR)
- FIRE BARRIER - (1 HR)
- SMOKE PARTITION
- EXIT
- OBSOLETE LINEN CHUTE
- HAZARDOUS AREA

SCB-A
7,516 S.F.
TRAVEL DISTANCE TO
SMOKE BARRIER = 130'

SCB-C
7,189 S.F.
TRAVEL DISTANCE TO
SMOKE BARRIER = 150'

SCB-B
13,312 S.F.
TRAVEL DISTANCE TO

BASEMENT

Drawing Title: BUILDING #15 BASEMENT	Project Title: FLOOR PLANS	Project Number: XX	Office of Construction and Facilities Management
Approved: U. S. DEPARTMENT OF VETERANS AFFAIRS VA MEDICAL CENTER MANCHESTER, NH 03104	Location: BUILDING #15	Building Number: BUILDING #15	
	Date: FEB 19, 2020 / Checked: FMS / Drawn: MTW	Drawing Number: A-150	
		Dwg. 17 of 20	

SC1-A
4,477 S.F.
TRAVEL DISTANCE TO
SMOKE BARRIER = 126'

SC1-C
4,569 S.F.
TRAVEL DISTANCE TO
SMOKE BARRIER = 152'

SC1-B
7,832 S.F.
TRAVEL DISTANCE TO
SMOKE BARRIER = 200'

NON-PATIENT CARE SUITE
173 SQ FT
TRAVEL DISTANCE TO EXIT
ACCESS DOOR = 18'

TOTAL SQUARE FOOTAGE
1,055sf

MATCHLINE G
MATCHLINE H
(SHEET 16 OF 18)

BUILDING 1

FIRE PROTECTION FEATURES
LIFE SAFETY PLAN

LEGEND

- FIRE BARRIER - (2 HR)
- FIRE BARRIER - (1 HR)
- SMOKE PARTITION
- EXIT
- OBSOLETE LINEN CHUTE
- HAZARDOUS AREA

FIRST FLOOR

Drawing Title: BUILDING #15 FIRST FLOOR	Project Title: FLOOR PLANS	Project Number: XX	Office of Construction and Facilities Management
Approved: U. S. DEPARTMENT OF VETERANS AFFAIRS VA MEDICAL CENTER MANCHESTER, NH 03104	Location: BUILDING #15	Building Number: BUILDING #15	
	Date: FEB 19, 2020 / Checked: FMS / Drawn: MTW	Drawing Number: A-151	
		Dwg. 18 of 20	

FIRE PROTECTION FEATURES
LIFE SAFETY PLAN

LEGEND

- FIRE BARRIER - (2 HR)
- FIRE BARRIER - (1 HR)
- SMOKE PARTITION
- EXIT
- OBSOLETE LINEN CHUTE
- HAZARDOUS AREA

MATCHLINE I
MATCHLINE J
(SHEET 17 OF 18)

EXAM ROOM D210
EXAM ROOM D211
ORTHOPEDICS OFFICE/EXAM D213
ORTHOPEDICS OFFICE/EXAM D223
PAIN MANAGER OFFICE/EXAM D226
CLEAN LINEN SUPPLY ROOM D230
PHOTOTHERAPH ROOM D231
DERMATOLOGY EXAM ROOM D233
DERMATOLOGY OFFICE/EXAM D235
DERMATOLOGY OFFICE/EXAM D236
EXAM ROOM D238
DERMATOLOGY EXAM ROOM D232
CIRCULATION C208
EXAM ROOM D239
CIRCULATION C207
PATIENT TOILET D234
EXAM ROOM D237
CIRCULATION C209
STORAGE ALCOVE C209A
EXAM ROOM D240
OFFICE D243
TRASH CLOSET D242
SOILED LINEN CLOSET D241
CIRCULATION C204C
CIRCULATION C209B
O2 STORAGE D209
STRETCHER ALCOVE C204A
SOILED LINEN CLOSET D214
STORAGE ALCOVE C204B
CIRCULATION C204
PATIENT TOILET D224
PHLEBOTOMY/EKG D225A
CIRCULATION C206
TELE/DATA CLOSET D252
EXAM ROOM D244
EXAM ROOM D245
SOILED UTILITY D212
STAFF TOILET D222
PHLEBOTOMY STATIONS D225
EQUIPMENT STORAGE ROOM D229
STORAGE D255
ELEVATOR LOBBY C201E
ELECTRICAL CLOSET D251
PODIATRY EXAM ROOM D206
PODIATRY EXAM ROOM D207
ORTHOPEDICS EXAM ROOM D215
HEALTH TECH WORKROOM D220
PAC STATION D221
STAFF LOCKER ROOM D246
RESIDENTS WORK ROOM D247
CIRCULATION C202
EXAM/OFFICE ROOM D208
ORTHOPEDICS EXAM ROOM D216
ORTHO/NEURO EXAM ROOM D228
CIRCULATION C210
WORKROOM D219
OFFICE D219A
MEN'S ROOM C201F
PODIATRY EXAM ROOM D205
PODIATRY EXAM ROOM D204
CIRCULATION C203
EXAM/ OFFICE ROOM D203
ORTHOPEDICS EXAM ROOM D217
RECEPTION D218
EXAM ROOM ORTHO/NEURO D227
WOMEN'S ROOM D254
CIRCULATION C201F
STAFF TOILET D250
PROGRAM MANAGER D248
HEALTH VET WORK STATION C201A
CONSULT ROOM D202
CIRCULATION C205
STAFF MULTIPURPOSE ROOM D249
CIRCULATION C201C
CIRCULATION C201B
PATIENT WAITING
PATIENT WAITING D201
WHEELCHAIR ALCOVE C201D
PATIENT TEACHING CONFRENCE ROOM D249A
CIRCULATION C201
STAIRS S2A
MATCHLINE I
MATCHLINE J

Drawing Title: BUILDING #15 SECOND FLOOR	Project Title: FLOOR PLANS	Project Number: XX	Office of Construction and Facilities Management
Approved: U. S. DEPARTMENT OF VETERANS AFFAIRS VA MEDICAL CENTER MANCHESTER, NH 03104	Location: BUILDING #15	Building Number: BUILDING #16	
	Date: FEB 19, 2020 / Checked: FMS / Drawn: MTW	Drawing Number: A-152	
		Dwg. 19 of 20	



FIRE PROTECTION FEATURES LIFE SAFETY PLAN

LEGEND

- FIRE BARRIER - (2 HR)
- FIRE BARRIER - (1 HR)
- SMOKE PARTITION
- EXIT
- (L) OBSOLETE LINEN CHUTE
- HAZARDOUS AREA

Drawing Title: FIRST FLOOR PLAN	Project Title: FLOOR PLANS	Project Number: XX	Office of Construction and Facilities Management
Approved: U. S. DEPARTMENT OF VETERANS AFFAIRS VA MEDICAL CENTER MANCHESTER, NH 03104	Location: BUILDING #18	Building Number: BUILDING #18	
	Date: FEB 19,2020 / Checked: FMS / Drawn: MTW	Drawing Number: A-181	
		Dwg. 20 of 20	